

Serial No.

To confirm the validity of the gas operative please contact CORGI on 0870 401 2300 or www.corgi-group.com

8489541

This inspection is for gas safety purposes only in accordance with The Gas Safety (Installation and Use) Regulations. Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has not been carried out.

CORGI

LANDLORD/HOME OWNER GAS SAFETY RECORD

Registered Business Details		CORGI REG NO	13618
Gas operative	<u>Nick Kelle</u>	(Print name)	
CORGI ID card serial No.	<u>706731601</u>		
Company	<u>Nick Kelle</u>		
Address	<u>36 Miltreid</u>		
	<u>THUR</u>		
Postcode	<u>TA554</u>	Tel No.	<u>01823 280032</u>

Job Address	
Name (Mr/Mrs/Miss/Ms)	<u>Agla Ffion</u>
Address	<u>Agla Ffion Church</u>
	<u>Agla Ffion</u>
Postcode	<u>TA554</u>
Tel No.	<u>01823 280032</u>

Landlord (or where appropriate their agent)	
Name (Mr/Mrs/Miss/Ms)	<u>Agla Ffion</u>
Address	<u>Agla Ffion Church</u>
	<u>Agla Ffion</u>
Postcode	<u>TA554</u>
Tel No.	<u>01823 280032</u>

APPLIANCE DETAILS										INSPECTION DETAILS				
Location	Appliance type	Make	Model	Flue type OF/RS/FL	Landlord's appliance (if applicable) Yes/No/NA	Appliance inspected Yes/No	Combustion analyser reading (if applicable)	Operating pressure in mbars or heat input kW/h or Btu/h	Safety device(s) correct operation Yes/No/NA	Ventilation provision satisfactory Yes/No	Visual condition of flue and termination satisfactory Yes/No/NA	Flue performance checks Pass/Fail/NA	Appliance serviced Yes/No	Appliance safe to use Yes/No
1 CHURCH	BOLICA(A) PORTERMAN		FLUVA 1005	RS	YES	YES	N/A	12.5 mbars	YES	YES	YES	N/A	YES	YES
2 CHURCH	BOLICA (B) PORTERMAN		FLUVA 1005	RS	YES	YES	N/A	11 mbars	YES	YES	YES	N/A	YES	YES
3														
4														
5														
DEFECT(S) IDENTIFIED						REMEDIAL ACTION TAKEN						Warning/Advice Notice issued Yes/No (if Yes* insert serial No.)		
1														
2	HEAT EXCHANGER + OUTLET FLUE													
3	POOR CONDITION					NONE ADVISED QUOTE TO FOLLOW								
4														
5														
						NEXT SAFETY CHECK DUE WITHIN 12 MONTHS								

Gas installation pipework satisfactory visual inspection Yes/No	☒ YES
Emergency Control accessible Yes/No	☒ YES
Satisfactory gas tightness test Yes/No/NA	☒ YES
Equipotential bonding satisfactory Yes/No	☒ YES

This Safety record is issued by: Signed <u>Nick Kelle</u>	Print name <u>Nick Kelle</u>
Received by: Signed _____	Tenant/Landlord/Agent/Home Owner
Date <u>15/02/08</u>	Number of appliances tested <u>2</u>