

Home Owner / Landlord Gas Safety Record

FT/GSR 3942000001063

Safety inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of flues (integrity, construction and lining) has been carried out.



Company / Installer		Installation		Client / Landlord	
Engineer	A Clarke	Name:	Treasurer	Name:	Treasurer
Address:	17 Hardys Road	Address:	Holy Trinity Church	Address:	Holy Trinity Church
	Bathpool		Ash Priors		Ash Priors
			Ash Priors		
	TAUNTON		TAUNTON		TAUNTON
Postcode:	TA2 8AY	Tel No:	07739437353	Postcode:	TA4 3NF
Gas Reg No:	590702	ID Card No:	-	Tel No:	-

Appliance Details					Inspection Details											
	Location	Appliance type	Make	Model	Flue type or RSFL	Landlord's Appliance Yes/No/NA	Appliance inspected Yes/No	Combustion Analyser reading CO/CO2	Operating pressure mBar or inches	Heat input in Btu/h or kW	Safety device (s) correct operation Yes/No/NA	Ventilation provision satisfactory Yes/No	Visual condition of flue and termination satisfactory Yes/No/NA	Flue performance test Pass/Fail/NA	Appliance serviced Yes/No	Appliance safe to use Yes/No
1	Main Hall	Boiler	Ideal	Vogue MAX System 32	R/S	Yes	Yes	9.4	19.6	32	Yes	Yes	Yes	Pass	Yes	Yes

Defects Identified															
No.	Defect Description														Label & Warning

Comments
- Gas Rate Max - 31.2 (net) - Co (ppm) 96 - O2 (%) 4.4 - Ratio 0.0010

Home Owner / Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of flues (integrity, construction and lining) has been carried out.

FT/GSR 3942000001063



Safety Checks

Is the emergency control valve access satisfactory? ☒
Outcome of gas installation pipework visual inspection ☒
Outcome of gas supply pipework visual inspection ☒
Number of appliance tested

Outcome of gas tightness test ☐
Is the protective equipotential bonding satisfactory? ☒
Approved CO alarm fitted ☒
Testing of CO alarm satisfactory ☒
Is CO alarm in date? ☒

Signature

Safety record issued by: Signed:

Adam Clarke

Print name Adam Clarke

Received by: Signed:

Adam Clarke

Print name Adam Clarke

NEXT INSPECTION DUE ON OR BEFORE

21/04/2027

Date: 21/04/2026